

_1

SERVICE BULLETIN

Page 1 of 7

MANDATORY

Improved Fuel Gravity Feed Hose

1.	Planning Information
----	----------------------

1.1 Effectivity: All AS202/18A/18A1/18A2/18A3/18A4 aircraft up to and including serial

number 236.

(Note: Some aircraft have Acro feed from right side tank only, some have Acro feed from both left and right side tanks).

1.2 Reason: Inconsistency of quality in hoses previously supplied.

1.3 Description The existing fuel gravity feed hose is replaced by a braided hose.

Due to the replacement hose being less flexible than the existing one, it is necessary to increase its length, and to shorten the length of the rigid tube to which it is attached, in order to retain the original position of the

intake valve.

1.4 Compliance At the next 100 hour inspection,

but not later than end of April

1993.

1.5 Approval Approved by the Swiss Federal

Office for Civil Aviation as an

Airworthiness Directive.

1.6 Time required Replacement only - approx. 1.0

hour per aerobatic tank .

With rework - approx 2.0 hours per


tank.

1.7 Material Materials are available from FFA.

FFA Flugzeugwerke Altenrhein AG CH-9423 Altenrhein Schweiz/Switzerland Telefon 071/43 51 11 Telex 88 29 06 ffa ch Telefax 071/43 53 30







> SERVICE BULLETIN

Page 2 of 7

1.8 Tooling

Standard tools, and facility for reworking rigid pipe as per diagram. (If rework facilities are not available, replacement parts may be ordered from FFA on an exchange basis).

1.9 Weight and Balance

Negligible

1.10 Electrical Load Data Not affected


1.11 Applicable Documents

AMM, Chapter 28. IPC, Chapter 28.

- 2. Procedure for AS202/18A1/18A2/18A3/18A4.
- 2.1 Drain fuel from right side or both tanks as necessary.
- 2.2 Remove inboard fuel level sensor from aerobatic tank(s), having ensured that relevant circuit breakers are OFF.
- 2.3 Disconnect rigid Acro fuel pipe in each applicable tank from the tank wall fitting and detach the spigots from the pipe support assembly.
- 2.4 Remove pipe assembly through the level sensor access hole.
- 2.5 Disassemble and discard the old flexible hose and spring. Retain the intake valve and clamps.
- 2.6 Obtain new rigid pipe assembly or rework the original pipe as per the attached drawing on page 7. (This involves shortening the tube by 80 mm. and reforming the bulged area). Remove any burrs.







SERVICE BULLETIN

Page 3 of 7

- 2.7 Assemble the new flexible hose assembly to the dimensions on the accompanying diagram on page 5, using the clamps and intake valve retained in step 2.5.
- 2.8 Refit the flexible hose assembly and sensor unit.
- 3. Material


Flexible Hose. 202-18.722.12 (Aeroquip 701-6, length 320 mm).

Suction pipe, LH 202-18.723 replacing 202-18.021 (LH pipe is optional equipment).

Suction pipe, RH 202-18.724 replacing 202-18.022

- 4. <u>Procedure for AS202/18A aircraft.</u> (Bonded Wing with metallic fuel tank).
- 4.1 Drain fuel from right side fuel tank.
- 4.2 Remove the fuel level sensor from the right side fuel tank, having first ensured that the relevant circuit breakers are OFF.
- 4.3 Disconnect the rigid Acro fuel pipe from the tank wall fitting and detach the spigots from the pipe support assembly.
- 4.4 Remove the pipe assembly through the level sensor access hole.
- 4.5 Disassemble, and discard the old flexible hose and spring. Retain the intake valve and clamps.
- 4.6 Rework the original pipe as per the attached drawing on page 6. (This involves shortening the tube by 80 mm.) Remove any burrs.





SERVICE BULLETIN

Page 4 of 7

- 4.7 Drill one 2mm hole in the attaching plate as per the accompanying diagram on page 6.
- 4.8 Assemble the new flexible hose assembly to the dimensions on the accompanying diagram on page 5 using the clamps and intake valve retained in step 4.5. Secure the flexible hose by attaching locking wire from the clamp to the 2mm hole in the fuel pipe attaching plate.
- 4.9 Refit the flexible hose assembly and sensor unit.
- 5. <u>Material</u>

Flexible Hose

202-18.722.12 (Aeroquip 701-6

length 320mm).

Locking wire,


Stainless steel, AISI302, length


app.200mm.

6. Recording

Execution of this Service Bulletin shall be entered in the aircraft maintenance log book.







ACRO FUEL PIPE MODIFICATION FOR AIRCRAFT AS202/18A1/18A2/18A3/18A4