Bundesamt für Zivilluftfahrt (BAZL) Office fédéral de l'aviation civile (OFAC) Ufficio federale dell'aviazione civile (UFAC) Federal Office for Civil Aviation (FOCA)

Lufttüchtigkeitsanweisung Consigne de navigabilité Prescrizione di aeronavigabilità Airworthiness directive

HB 96-140

Inkraftsetzung Mise en vigueur Entrata in vigore Effective Date

18.03.1996

SUPERSEDED
BY FOCA AD:
HB 97 - 001

Betroffene Muster - Types concernés - Applicabilità - Models affected

PILATUS AIRCRAFT LTD.- Model PC-12 aircraft, Serial Numbers: S/N 101 up to and including S/N 135.

Anlass/Massnahmen - Objet/Mesures - Oggetto/Provvedimenti - Subject/Action

MAGNETIC COMPASS DEVIATION

Re-routing and replacement of the Starter-Generator

and Generator 2 power return cables.

Temporary Pilot's Operating Handbook revision.

Fristen - Délais - Scadenza - Compliance

Compliance as indicated on page 2 of this Airworthiness Directive.

Herkunft - Provenance - Provenienza - Origin

Bezugnahme - Référence - Riferimento - Reference

- Pilatus PC-12 Service Bulletin No.: 24-002 dated March 7,1996

- Pilatus PC-12 Pilot's Operating Handbook -

Temporary Revision dated March 07, 1996

(Pilatus Report No.: 01973-001 / POH Section 2 and 3)

Bemerkungen - Observations - Osservazioni - Remarks

Rechtsmittelbelehrung siehe TM Nr.
Voies de droit voir CT no.

Rimedi giuridici vedi CT no.

Right to appeal see CT no.

Seite von
Page 1 de 2
Pagina di
Page of

FOCA AD

HB 96 - 140

Lufttüchtigkeitsanweisung Consigne de navigabilité Prescrizione di aeronavigabilità Airworthiness directive

BAZL Schweiz
OFAC Suisse
UFAC Svizzera
FOCA Switzerland

## Reason

In the event of an Attitude and Heading Reference System (AHRS) failure in IMC conditions, the pilot must immediately revert to the standby instruments. In aircraft which are equipped for flight in known icing conditions, the magnetic compass deviation caused by the additional electrical loads has been found to be too great to be an acceptable standby heading reference.

## Action

The actions specified in this AD are inteded to to reduce the compass deviation to acceptable limits under all operating conditions. A modification to the aircraft electrical system has been developed which consists of re-routing and replacement of the Starter-Generator and Generator 2 power return cables and requires the insertion of a Temporary Revision into the Pilot's Operating Handbook.

## **Compliance**

- (1) For aircraft modified to fly into known icing conditions:
  (Aircraft incorporating PC-12 SB No.: 30-001 (Icing Modification)
  - Prior to next flight into IMC conditions but not later than September 30, 1996; Incorporate Pilatus PC-12 Service Bulletin No.: 24-002 dated March 07, 1996
- (2) For aircraft **not modified** to fly into known icing conditions:
  (Aircraft **not** incorporating PC-12 SB No.: 30-001 (Icing Modification)
- Before or together with the incorporation of PC-12 SB No.: 30-001 (Icing Modification) but not later than September 30, 1996; Incorporate Pilatus PC-12 Service Bulletin No.: 24-002 dated March 07, 1996

## FOR FURTHER INFORMATION CONTACT:

Federal Office for Civil Aviation (FOCA) Type Certification Section (FM), Maulbeerstrasse 9, CH-3003 Berne, Switzerland / Facsimile ( + 41) 31 325 80 48