Bundesamt für Zivilluftfahrt (BAZL) Office fédéral de l'aviation civile (OFAC) Ufficio federale dell'aviazione civile (UFAC) Federal Office for Civil Aviation (FOCA) Maulbeerstasse 9 CH-3003 Berne Switzerland Inkraftsetzung Mise en vigueur Tetrata in vigueur		Lufttüchtigkeitsanweisung (LTA) Consigne de Navigabilité (CN) Prescrizione di Aeronavigabilità (PA) Airworthiness Directive (AD)	FOCA AD HB-2005-079	
	18 February 2005	PILATUS – PC-12 FOCA TC/TCDS No: F56-30 ATA 30 – ICE AND RAIN PROTECTION		

Issue date: 11 February 2005

Subject: WINDSHIELD DEICE SYSTEM WIRING – Inspection / Replacement

Superseded/Revised ADs: Not applicable

1. APPLICABILITY:

PILATUS AIRCRAFT LTD.

Model PC-12 and PC-12/45 airplanes, Manufacturer Serial Numbers (MSN) 322 thru MSN 400 inclusive.

2. REASON:

This Airworthiness Directive (AD) is prompted after a report of a Co-Pilots windshield deices system failure. The cause of the defect was found in an overheating of the return wire from the windshield heating system. Investigation revealed that the installation of the wiring in question was not in accordance with the specifications given in the applicable wiring diagrams (incorrect American Wire Gage [AWG]). This could result in heat damage of the concerned wiring and as a consequence, electrical arcing or possible fire in the overhead panel in the flight-compartment.

In order to correct the condition described, this AD requires the inspection for signs of heat damage of electrical parts and for cables of incorrect AWG and the replacement of heat damaged parts and wires, if necessary.

3. COMPLIANCE / ACTION:

Required as indicated below, unless already accomplished:

Within the next 10 hours time-in-service but not later than three calendar months after the effective date of this AD:

3.1. INSPECTION / REPLACEMENT

- 3.1.1. Perform an inspection for signs of heat damage of the wires, splices and related link wires in the area of terminal block (TB152) in accordance of paragraph 3 of PILATUS PC-12 Service Bulletin No. 30-009. No heat damage is permitted.
- 3.1.2. Perform a check of the wires and related link wires to verify that wires of correct size (AWG) are installed as specified.
- 3.1.3. If any signs of heat damage or incorrect wiring are found during the inspection required by paragraph 3.1.1. and 3.1.2. of this AD, prior to further flight, replace them in accordance with PILATUS PC-12 Service Bulletin No. 30-009.

./.

Rechtsmittelbelehrung Voies de droit Rimedi giuridici Right to appeal	Nr. o. o. o.		Seite Page Pagina Page	1	von de di of	2
--	-----------------------	--	---------------------------------	---	-----------------------	---

FOCA AD

HB-2005-079

Lufttüchtigkeitsanweisung (LTA)
Consigne de Navigabilité (CN)
Prescrizione di Aeronavigabilità (PA)
Airworthiness Directive (AD)



BAZL Schweiz OFAC Suisse UFAC Svizzera FOCA Switzerland

4. REF. PUBLICATIONS:

The actions required by this AD shall be done in accordance with the manufacturer's documentation listed in this paragraph, and/or later revisions approved by the Swiss Federal Office for Civil Aviation (FOCA):

Manufacturer's Documentation

PILATUS PC-12 Service Bulletin No. 30-009, dated 25 January 2005

The applicable manufacturer's documentation may be obtained directly from:

 PILATUS AIRCRAFT LTD.
 TEL No.: +41 41 619 6208

 CH-6371 STANS, Switzerland
 FAX No.: +41 41 619 7311

CUSTOMER SUPPORT MANAGER Email: SupportPC12@pilatus-aircraft.com

5. FOR FURTHER INFORMATION CONTACT:

FEDERAL OFFICE FOR CIVIL AVIATION (FOCA)

Design and Production (STEH)

Maulbeerstrasse 9 FAX No.: +41 31 325 9324 (or) CH-3003 Berne, Switzerland FAX No.: +41 31 322 5918