

TEMPORARY REVISION NO. 04-13

Date: Jun 15/05

Filing Instructions:

Insert in front of 04-00-00, page 1, dated Apr 30/05 and add the details on the Record of Temporary Revisions Sheet in the front of the manual.

Important:

Do not remove this Temporary Revision unless instructed to do so by:

- The Highlights of a normal revision
- A new Temporary Revision which supersedes this one

Reason for Issue:

This Temporary Revision is issued to:

- To add life limits for the backrest tubes on crew seats with and without a recline system installed.

Action:

New Component Limitations are given as follows:

Component	Life
Backrest tubes on Crew Seats with a recline system (Seat Part No's 959.30.01.111, 112, 121 and 122)	5000 flying hours
Backrest tubes on Crew Seats without a recline system (Seat Part No's 959.30.01.131, 132, 133 and 134)	10000 flying hours

Compliance:

For crew seats with a backrest recline system (Part No's 959.30.01.111, 112, 121 and 122) within 100 flying hours or 3 months, whichever comes first, from the date of this Temporary Revision.

For crew seats without a backrest recline system (Part No's 959.30.01.131, 132, 133 and 134) within 500 flying hours or by the end of 2005, whichever comes first, from the date of this Temporary Revision.

Follow up action:

Return all the replaced backrest tubes to Pilatus Aircraft Ltd, Structural Analysis Group ECE, CH-6371 Stans, Switzerland and give the following information:

- The crew seat Part Number and Serial Number
- The aircraft MSN
- The aircraft flying hours and number of flights
- The replacement date of the backrest tube

EFFECTIVITY: All

04-00-00