

Federal Department of the Environment, Transport, Energy and Communications DETEC

Federal Office of Civil Aviation FOCA

Safety Division - Aircraft

Swiss Confederation

Lufttüchtigkeitsanweisung (LTA) Consigne de Navigabilité (CN) Direttive sulla Navigabilità (DN) Airworthiness Directive (AD)		FOCA AD HB-2011-002
Inkraftsetzung Mise en vigueur Entrata in vigore Effective Date	24 May 2011	Pilatus – PC-21 FOCA TC/TCDS No: F 56-35

Issue Date: 10 May 2011

ATA Chapter: ATA 71 – Power Plant

Subject: Power Plant – Shock Mounting Bolts – Identification

Supersedure / Revised

AD(s):

Not applicable

Type Certificate Holder's Name:

Pilatus Aircraft Ltd.

Manufacturer(s): Pilatus Aircraft Ltd.

Applicability: Model PC-21 aircraft, Manufacturer Serial Numbers (MSN) 101 through

MSN 127 inclusive.

Reason: This Airworthiness Directive (AD) is prompted due to the discovery of

a engine shock mount bolt which had lost the cadmium plating at some locations. The bolt has been traced to a certain batch and is manufactured with a vacuum plating process. Due to the damaged bolt surface, the pos-

sibility of corrosion is increased.

Such a condition, if left uncorrected, could lead to failure of the bolt and

will prejudice the structural integrity of the aircraft.

In order to correct and control the situation, this AD requires a one-time check of the engine shock mount bolt batch numbers and, if necessary,

the replacement of the affected bolts.

Required Action(s) and Compliance Time(s):

Required as indicated below, unless already accomplished:

- (1) At the next planned annual inspection but not later than 12 month after the effective date of this AD, check the batch number of the engine shock mount bolts (P/N 571.20.21.066) as required by paragraph (§) 3.B. of PILATUS PC-21 Service Bulletin No. 71-005.
- (2) If during the inspection required by § (1) of this AD, bolts with the batch number 415196 are found, prior to further flight, replace the affected bolts in accordance with (§) 3.C. of PILATUS PC-21 Service Bulletin No. 71-005.
- (3) After the effective date of this AD, engine shock mount bolts with batch number 415196 shall not be installed on any aircraft.

Lufttüchtigkeitsanweisung (LTA) Consigne de Navigabilité (CN) Direttive sulla Navigabilità (DN) Airworthiness Directive (AD) FOCA AD

HB-2011-002

Ref. Publication(s): PILATUS PC-21 Service Bulletin No. 71-005, initial issue.

The use of later approved revisions of this document is acceptable for

compliance with the requirements of this AD.

For further information contact:

The applicable manufacturer's documentation may be obtained directly

from:

PILATUS AIRCRAFT LTD.

Customer Technical Support (MCC)

P.O. Box 992

CH-6371 Stans, Switzerland

Tel.: +41 (0)41 619 33 03 Fax: +41 (0)41 619 67 73

E-mail: Techsupport@pilatus-aircraft.com

For further information contact:

FEDERAL OFFICE OF CIVIL AVIATION (FOCA)

Design and Production (STEH) CH-3003 Bern, Switzerland

Fax: +41 (0) 31 322 59 18 E-mail: <u>airdir@bazl.admin.ch</u>