

PILATUS AIRCRAFT LTD, STANS, SWITZERLAND

SERVICE BULLETIN

PC-21

Service Bulletin No: 34-005 Ref No: 85

Modification No: EC-12-0334, EC-12-0541 ATA Chapter: 34

NAVIGATION - FLIGHT ENVIRONMENT DATA MODIFICATION TO THE PITOT SYSTEM

1. Planning Information

A. Effectivity

MSNs 101 thru 154.

NOTE: The intent of this modification will be incorporated during production on MSN 155 and subsequent.

B. Concurrent Requirements

None.

C. Reason

(1) Problem

One operator has reported false pitot-pressure inputs to the air data system.

(2) Cause

An investigation found that the pitot system had become blocked due to water ingress.

(3) Solution

Introduction of an inertial water separator which prevents ingression of water into the pitot tubing in the wing.

D. Description

This Service Bulletin gives the instructions and data necessary to do the modification to the aircraft pitot system.

Revision No. 1 of this Service Bulletin is issued to correct the size, and therefore, the part number of the screw and washer that attaches the clip (which holds the electrical wires) to the water container. New kits have been created to include these new parts.

A note has also been added to make sure the new holes in the main spar are drilled in the correct position.

Operators that have accomplished this Service Bulletin at the initial issue must return to the work area and do the steps listed in Para. 4.

E. Compliance

Mandatory.

Accomplishment required not later than 31 December 2012.

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1.
 Date:
 Nov 30/12
 Page
 1 of 18





F. Approval

The technical content of this Service Bulletin is approved under the authority of Letter of DOA Acceptance ref. FOCA. 21J.002.

PILATUS advises Operators/Owners to check with their designated Airworthiness Authorities for any changes, local regulations or sanctions that may affect the embodiment of this Service Bulletin.

G. Copyright

© Pilatus Aircraft Ltd. This document contains proprietary information that is protected by copyright. All rights are reserved. No part of this document may be copied, reproduced or translated to other languages without the prior written consent of Pilatus Aircraft Ltd.

H. Manpower

	Man-Hours
Preparation	1.0
Modification	6.0
Close up	3.0
TOTAL MAN-HOURS	10.0

NOTE: Man-hours figures do not include the time required to cure sealants and adhesives.

I. Weight and Balance

(1) Weight Change

+ 0.460 kg (+ 1.014 lb).

(2) Moment Change

+ 2.10 kgm (+ 15.19 lb ft).

J. Electrical Load Data

Not changed.

K. Software

Not changed.

L. References

Aircraft Maintenance Manual (AMM), 00-50-00-00A-013A-A, 06-40-00-00A-055A-A, 34-11-00-00A-364A-A, 95-00-00-00A-012A-A.

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1.
 Date:
 Nov 30/12
 Page
 2 of 18



M. Publications Affected

AMM, 05-40-00-00A-288A-A, 34-11-00-00A-040A-A, 34-11-00-00A-054A-A, 34-11-00-00A-055A-A, 34-11-00-00A-226A-A, 34-11-01-00A-520A-A, 34-11-01-00A-720A-A.

Illustrated Parts Data (IPD), 21-B-34-11-00-010-941A-A or 21-C-34-11-00-01C-941A-A or 21-D-34-11-00-01D-941A-A.

N. Interchangeability of Parts

One way interchangeable. Pre-Service Bulletin 34-005 parts must not be installed on post-Service Bulletin 34-005 aircraft.

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1.
 Date:
 Nov 30/12
 Page
 3 of 18



2. Material Information

A. Material - Price and Availability

Operators who require more information should contact:

PILATUS AIRCRAFT LTD,
MANAGER, INTEGRATED LOGISTIC SUPPORT
CH 6371 STANS, Tel: +41 41 619 34 07
SWITZERLAND Fax:+41 41 619 64 52

Operators are requested to advise Pilatus Aircraft Ltd. of the Manufacturer's Serial Number (MSN), the flying hours and landings of aircraft which are allocated for this Service Bulletin using the Service Bulletin Evaluation Form.

Kit Number	Price	Availability
For Config 1 Aircraft:		
500.50.21.081	Contact address above	Contact address above
500.55.21.001	Contact address above	Contact address above
For Config 2 Aircraft		
500.50.21.082	Contact address above	Contact address above
500.55.21.001	Contact address above	Contact address above

NOTE: Config 1 aircraft are MSN 128 thru MSN 152.

Config 2 aircraft are MSN 101 thru MSN 127, MSN 153 and MSN 154.

Kits P/N 500.50.21.081 and P/N 500.50.21.082 are one per aircraft. Kits P/N 500.55.21.001 are one per fleet of aircraft.

B. Material Necessary for Each Aircraft


(1) Material to be Purchased

(a) Modification Kit No. 500.50.21.081 has these parts:

New Part No.	Description	Old Part No.	Qty	Disp. Code	Fig	Item
534.11.21.024	ATTACHMENT ANGLE		1		3	29
534.11.21.029	BRACKET		1		3	25
534.11.21.023	BRACKET		1		3	27
534.11.21.035	CLOTH, ABSORBING		1		3	1
534.11.21.036	HUMIDITY INDICATOR		1		3	2
534.11.21.037	TANK COVER ASSY		1		3	4
534.11.21.027	TUBE ASSY		1		3	7

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1.
 Date:
 Nov 30/12
 Page
 4 of 18





I

PC-21

New Part No.	Description	Old Part No.	Qty	Disp. Code	Fig	Item
534.11.21.021	WATER CONTAINER		1		3	24
932.19.21.027	BOLT		4 4		3	28 42
935.63.12.064	SCREW		1		3	18
935.63.11.064	SCREW		1		3	6
935.63.11.066	SCREW		2		3	26
938.07.68.303	NUT		1 2		3	21 39
938.07.68.304	NUT		4 4		3	31 33
938.77.11.113	WASHER		4 4		3	30 32
938.77.11.111	WASHER		1 2		3	22 40
938.77.11.112	WASHER		1		3	19
938.77.11.110	WASHER		1		3	12
946.01.17.101	FITTING		1		3	Note 1
946.01.17.197	INSERT		1		3	17
946.20.85.202	FITTING		1 1		3	15 23
946.31.05.117	CLAMP		1 1		3	8 14
946.31.05.703	CABLE CLIP		1		3	20
946.91.26.130	PACKING, PREFORMED		1		3	3
6302.0048.03	WASHER, LOCKING		1		3	41

NOTE 1: The fitting (P/N 946.01.17.101) is made up of items 16, 36 and 37.

NOTE 2: Part Numbers given in this Service Bulletin are correct at the time of approval. Pilatus Aircraft Ltd. reserves the right to change the part numbers as necessary. Part numbers of items delivered with the Modification Kit are correct when the kit is dispatched. This could lead to differences between those part numbers quoted in this Service Bulletin and the Modification Kit if parts are superseded. Operators are requested to check the IPC for delivered parts which differ from those listed in the Service Bulletin Materials Kit List.

Service Bulletin No: 34-005 Rev. No. 1. Date: Nov 30/12 Date: Sep 22/12 Page 5 of 18



I

PC-21

Date: Sep 22/12

6 of 18

Page

(b) Modification Kit No. 500.50.21.082 has these parts:

New Part No.	Description	Old Part No.	Qty	Disp. Code	Fig	Item
533.47.21.033	BUSH		1		3	11
935.63.11.068	SCREW		1		3	13
534.11.21.024	ATTACHMENT ANGLE		1		3	29
534.11.21.029	BRACKET		1		3	25
534.11.21.023	BRACKET		1		3	27
534.11.21.035	CLOTH, ABSORBING		1		3	1
534.11.21.036	HUMIDITY INDICATOR		1		3	2
534.11.21.037	TANK COVER ASSY		1		3	4
534.11.21.027	TUBE ASSY		1		3	7
534.11.21.021	WATER CONTAINER		1		3	24
932.19.21.027	BOLT		4 4		3	28 42
935.63.12.064	SCREW		1		3	18
935.63.11.064	SCREW		1		3	6
935.63.11.066	SCREW		2		3	26
938.07.68.303	NUT		1 2		3	21 39
938.07.68.304	NUT		4 4		3	31 33
938.77.11.113	WASHER		4 4		3	30 32
938.77.11.111	WASHER		1 2		3	22 40
938.77.11.112	WASHER		1		3	19
938.77.11.110	WASHER		1		3	12
946.01.17.101	FITTING		1		3	Note 1
946.01.17.197	INSERT		1		3	17
946.20.85.202	FITTING		1 1		3	15 23
946.31.05.117	CLAMP		1		3	8 14
946.31.05.703	CABLE CLIP		1		3	20
946.91.26.130	PACKING, PREFORMED		1		3	3
6302.0048.03	WASHER, LOCKING		1		3	41

Service Bulletin No: 34-005 Rev. No. 1. Date: Nov 30/12







NOTE 1: The fitting (P/N 946.01.17.101) is made up of items 16, 36 and 37.

NOTE 2: Part Numbers given in this Service Bulletin are correct at the time of approval. Pilatus Aircraft Ltd. reserves the right to change the part numbers as necessary. Part numbers of items delivered with the Modification Kit are correct when the kit is dispatched. This could lead to differences between those part numbers quoted in this Service Bulletin and the Modification Kit if parts are superseded. Operators are requested to check the IPC for delivered parts which differ from those listed in the Service Bulletin Materials Kit List.

(c) Template Kit No. 500.55.21.001 has these parts:

New Part No.	Description	Old Part No.	Qty	Disp. Code	Fig	Item
513.34.21.030	HOLE TEMPLATE		1		2	5
935.63.11.066	SCREW		4		2	4
938.77.61.011	WASHER		4		2	3

NOTE: Part Numbers given in this Service Bulletin are correct at the time of approval. Pilatus Aircraft Ltd. reserves the right to change the part numbers as necessary. Part numbers of items delivered with the Modification Kit are correct when the kit is dispatched. This could lead to differences between those part numbers quoted in this Service Bulletin and the Modification Kit if parts are superseded. Operators are requested to check the IPC for delivered parts which differ from those listed in the Service Bulletin Materials Kit List.

(2) Operator Supplied Materials (Ref. AMM 00-50-00-00A-013A-A)

MATERIAL NO.	DESCRIPTION	QTY	REMARKS
P01-010	SOLVENT	A/R	Or equivalent
P02-001	LOCKWIRE	A/R	Or equivalent
P02-031	ABSORBENT PAPER	A/R	Or equivalent
P07-021	ALODINE 1132	A/R	Or equivalent
-	STRING	A/R	Or equivalent, Local Supply
-	REAMER, 5.1 MM	A/R	Local Supply

C. Material Necessary for Each Spare

None

D. Re-identified Parts


None

E. Tooling - Cost and Availability

Refer to Para. 2.B.(1)(c).

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1. Date:
 Nov 30/12
 Page 7 of 18





3. Accomplishment Instructions

WARNING: MAKE SURE THAT BOTH EJECTION SEATS HAVE THE SAFETY PINS INSTALLED IN THE SAFE FOR SERVICING LOCATIONS AND THAT THE CFS HAS THE SAFETY PIN INSTALLED IN THE SAFE POSITION BEFORE YOU GO INTO THE COCKPIT (REF. AMM, 95-00-00-00A-012A-A).

WARNING: READ AND OBEY THE MANUFACTURERS HEALTH INSTRUCTIONS BEFORE YOU USE THE CONSUMABLE MATERIALS.

NOTE: Read and obey the manufacturers instructions about how to prepare the consumable materials before you use them.

NOTE: To accomplish this Service Bulletin, you will require:

- The mechanics tool kit. P/N 990.00.02.004
- The metal works tool kit, P/N 990.00.02.011.

A. Preparation

NOTE: For the location of the access items, refer to AMM, 06-40-00-00A-055A-A.

Remove the access panels RB38 and RB39.

B. Modification

NOTE: Config 1 aircraft are MSN 128 thru MSN 152.

Config 2 aircraft are MSN 101 thru MSN 127, MSN 153 and MSN 154.

- (1) Disconnect the plastic tube assembly (Ref. Fig. 1)
 - (a) Cut and remove the cable ties (7) that attach the electrical wires (6) to the tube (1) between the pitot tube and the wing spar.
 - (b) Disconnect the nut (2) from the fitting (4).
 - (c) Disconnect the fitting (4) from the pitot tube (5).
 - (d) Remove, and discard, the insert (3), the fitting (4) and the nut (2).
 - (e) For Config 1 aircraft:
 - 1 Remove the screw (13), the washer (14), the bush (11), the special washer (10) and the attachment (9) from the angle (8).
 - 2 Remove the clamp (12) from the tube (1).
 - <u>3</u> Discard the washer (14) and the clamp (12). Keep the screw (13), the bush (11), the special washer (10) and the attachment (9).
 - (f) For Config 2 aircraft:
 - 1 Remove the screw (13), the washer (14), the special washer (10) and the attachment (9) from the angle (8).

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1.
 Date:
 Nov 30/12
 Page
 8 of 18





- 2 Remove the clamp (12) from the tube (1).
- <u>3</u> Discard the screw, (13,) the clamp (12) and the washer (14). Keep the special washer (10) and the attachment (9).
- (2) Make the holes in the main spar (Ref. Fig. 2):
 - (a) Remove the four screws (2).
 - (b) Use the string (or equivalent local supply) and tie the two terminal blocks (1) clear of the work area.

NOTE: This is to keep the strain from the cables of the terminal blocks (1).

- (c) Put the hole template (5) (P/N 513.34.21.030) in position on the wing main spar (6).
- (d) Use the screws (4) (P/N 935.63.11.066) and the washers (3) (P/N 938.77.61.011) to keep the hole template (5) (P/N 513.34.21.030) in position.

NOTE: Make sure that when you drill the four holes for the attachment angle (Fig 3, Item 29) (P/N 534.11.21.024), they do not go through the joggle in the structure. Loosen the screws (4) (P/N 935.63.11.066) and move the position of the template (5) (P/N 513.34.21.030) to make sure you do not drill through the joggle. Tighten the screws (4) (P/N 935.63.11.066).

- (e) Drill four 3.2 mm holes for the attachment angle (Fig 3, Item 29) (P/N 534.11.21.024).
- (f) Remove:
 - The screws (4) (P/N 935.63.11.066)
 - The washers (3) (P/N 938.77.61.011)
 - The hole template (5) (P/N 513.34.21.030).
- (g) Use a 4.8 drill and make the four holes in the main spar (6) larger.
- (h) Use the 5.1 reamer and make the four holes in the main spar (6) larger.
- (i) Make sure there are no sharp edges.
- (j) Use the absorbent paper (Mat. No. P02-031) made moist with the solvent (Mat. No. P01-010) and clean the area.
- (k) Apply a layer of the Alodine 1132 (Mat. No. P07-021) to the bare metal of the holes.
- (I) Remove the string (or equivalent) and put the two terminal blocks (1) in the correct position for installation.
- (m) Install the four screws (2).

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1.
 Date:
 Nov 30/12
 Page
 9 of 18





- (3) Install the modified system parts (Ref. Fig. 3)
 - (a) Put the packing (3) (P/N 946.91.26.130) in the groove on the tank cover assy (4) (P/N 534.11.21.037).
 - (b) Put the absorbing cloth (1) (P/N 534.11.21.035) in the water container (24) (P/N 534.11.21.021).
 - (c) Put the humidity indicator (2) (P/N 534.11.21.036) on the window of the tank cover assy (4) (P/N 534.11.21.037).
 - (d) Install the tank cover assy (4) (P/N 534.11.21.037) in the water container (24) (P/N 534.11.21.021).
 - (e) Put the bracket (25) (P/N 534.11.21.029) and the bracket (27) (P/N 534.11.21.023) around the water container (24) (P/N 534.11.21.021) and loosely install:
 - 1 On the inboard side:
 - The screw (26) (P/N 935.63.11.066)
 - The washer (40) (P/N 938.77.11.111)
 - The nut (39) (P/N 938.07.68.303).
 - 2 On the outboard side:
 - The screw (26) (P/N 935.63.11.066)
 - The locking washer (41) (P/N 6302.0048.03)
 - The washer (40) (P/N 938.77.11.111)
 - The nut (39) (P/N 938.07.68.303).
 - (f) Put the attachment angle (29) (P/N 534.11.21.024) in the correct position for installation on the bracket (27) (P/N 534.11.21.023).
 - (g) Loosely install the four bolts (42) (P/N 932.19.21.027), the four washers (30) (P/N 938.77.11.113) and the four nuts (31) (P/N 938.07.68.304).
 - (h) Install the fitting (23) (P/N 946.20.85.202) in the water container (24) (P/N 534.11.21.021).
 - (i) Put the clamp (8) (P/N 946.31.05.117) on the tube assembly (7) (P/N 534.11.21.027).
 - (j) Put the clamp (8) (P/N 946.31.05.117) in position against the lug on the water container (24) (P/N 534.11.21.021).
 - (k) Connect the tube assembly (7) (P/N 534.11.21.027) to the fitting (23) (P/N 946.20.85.202) installed on the water container (24) (P/N 534.11.21.021).
 - (I) Install the screw (6) (P/N 935.63.11.064), the washer (22) (P/N 938.77.11.111) and the nut (21) (P/N 938.07.68.303).

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1.
 Date:
 Nov 30/12
 Page
 10 of 18





(m) For Config 1 Aircraft:

Put the clamp (14) (P/N 946.31.05.117) on the tube assembly (7) (P/N 534.11.21.027) and install:

- The screw (13)
- The washer (12) (P/N 938.77.11.110)
- The bush (11)
- The special washer (10)
- The attachment (9).

NOTE: The screw (13), the bush (11), the special washer (10) and the attachment (9) were kept in the removal paragraph (Ref. Para. 3.B.(1)(e)3).

(n) For Config 2 Aircraft:

Put the clamp (14) (P/N 946.31.05.117) on the tube assembly (7) (P/N 534.11.21.027) and install:

- The screw (13) (P/N 935.63.11.068)
- The washer (12) (P/N 938.77.11.110)
- The bush (11) (P/N 533.47.21.033)
- The special washer (10)
- The attachment (9).

NOTE: The special washer (10) and the attachment (9) were kept in the removal paragraph (Ref. Para. 3.B.(1)(f)3).

- (o) Connect the tube assembly (7) (P/N 534.11.21.027) to the pitot tube (5).
- (p) Put the attachment angle (29) (P/N 534.11.21.024) in the correct position against the main spar (34).
- (q) Install the four bolts (28) (P/N 932.19.21.027), the four washers (32) (P/N 938.77.11.113) and the four nuts (33) (P/N 938.07.68.304).
- (r) Tighten the four nuts (31) (P/N 938.07.68.304).
- (s) Tighten the two nuts (39) (P/N 938.07.68.303).
- (t) Use the lockwire (Mat. No. P02-001) and safety the tank cover assy (4) (P/N 534.11.21.037) to the locking washer (41) (P/N 6302.0048.03).
- (u) Connect the tube assembly (7) (P/N 534.11.21.027) to the fitting (15) (P/N 946.20.85.202).
- (v) Disassemble the fitting (P/N 946.01.17.101).

NOTE: The fitting (P/N 946.01.17.101) is made up of items 16, 36 and 37.

(w) Connect the connector (16) (part of the fitting (P/N 946.01.17.101)) to the fitting (15) (P/N 946.20.85.202).

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1.
 Date:
 Nov 30/12
 Page
 11 of 18





- (x) Put the plastic pitot tube (35) in position against the fitting (15) (P/N 946.20.85.202).
- (y) Make a mark on the plastic pitot tube (35) to show this position.
- (z) Cut the plastic tube (35) at the position marked in the previous Step.
- (aa) Put the nut (36) (part of the fitting (P/N 946.01.17.101)) on the plastic tube (35).
- (ab) Put the sleeve (37) (part of the fitting (P/N 946.01.17.101)) on the plastic tube (35).
- (ac) Put the insert (17) (P/N 946.01.17.197) in the end of the plastic tube (35).
- (ad) Connect the nut (36) (part of the fitting (P/N 946.01.17.101)) to the connector (16) (part of the fitting (P/N 946.01.17.101)).
- (ae) Put the clamp (20) (P/N 946.31.05.703) on the electrical wires (43) to the pitot tube.
- (af) Put the clamp (20) (P/N 946.31.05.703) against the water container (24) (P/N 534.11.21.021) and install the screw (18) (P/N 935.63.12.064) and the washer (19) (P/N 938.77.11.112).

C. Close-Up

(1) Do the pitot-system leak-check (Ref. AMM, 34-11-00-00A-364A-A).

NOTE: For the location of the access items, refer to AMM, 06-40-00-00A-055A-A.

(2) Install the access panels RB38 and RB39.

D. Documentation

- (1) Make an entry in the Aircraft Logbook that this Service Bulletin has been incorporated.
- (2) Use the Service Bulletin Evaluation Sheet and report your results and the serial number of the aircraft to PILATUS.

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1.
 Date:
 Nov 30/12
 Page
 12 of 18





4. Accomplishment Instructions

NOTE: These instructions are only applicable to aircraft that have had this Service Bulletin accomplished at the Initial Issue.

WARNING: MAKE SURE THAT BOTH EJECTION SEATS HAVE THE SAFETY PINS INSTALLED IN THE SAFE FOR SERVICING LOCATIONS AND THAT THE CFS HAS THE SAFETY PIN INSTALLED IN THE SAFE POSITION BEFORE YOU GO INTO THE COCKPIT (REF. AMM, 95-00-00-00A-012A-A).

NOTE: To accomplish this part of the Service Bulletin, you will require the mechanics tool kit, P/N 990.00.02.004

A. Preparation

NOTE: For the location of the access items, refer to AMM, 06-40-00-00A-055A-A.

Remove the access panels RB38.

B. Modification

- (1) Remove the screw (18) (P/N 935.63.11.062) and the washer (19) (P/N 938.77.11.111).
- (2) Make sure the clamp (20) (P/N 946.31.05.703) stays in position around the electrical wires.
- (3) Discard the screw (18) (P/N 935.63.11.062) and the washer (19) (P/N 938.77.11.111).
- (4) Put the clamp (20) (P/N 946.31.05.703) against the water container (24) (P/N 534.11.21.021) and install the new screw (18) (P/N 935.63.12.064) and the new washer (19) (P/N 938.77.11.112).

C. Close-Up

- (1) Remove all equipment, tools and materials from the work area. Make sure that the work area is clean.
- (2) Install the access panels RB38.

D. Documentation

- (1) Make an entry in the Aircraft Logbook that Para. 4 of this Service Bulletin has been accomplished.
- (2) Use the Service Bulletin Evaluation Sheet and report your results and the serial number of the aircraft to PILATUS.

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1.
 Date:
 Nov 30/12
 Page
 13 of 18






Date: Sep 22/12


14 of 18

Page



Service Bulletin No: 34-005 Rev. No. 1. Date: Nov 30/12






Service Bulletin No: 34-005 Rev. No. 1. Date: Nov 30/12 Date: Sep 22/12 Page 15 of 18







Service Bulletin No: 34-005 Rev. No. 1. Date: Nov 30/12 Date: Sep 22/12 Page 16 of 18



SERVICE BULLETIN EVALUATION SHEET FOR SB No. 34-005									
Title	Navigation - Flight Environment Data Modification to the Pitot System								
Customer									
Service Center									
	EMBODIMENT REPORTING								
This SB has been embodied: On the entire fleet Only partially									
Provide embodime	ent details per	aircraft (use a	dditio	nal copies o	of this table, if necessary)				
MSN	Flying	Hours	MSN Flying I		Flying Hours				
Additional embo	diment comr	nents/findings	S						
(p		EDITORIAL C quality, sugg			nents, etc.)				
(procedure, kit quality, suggested improvements, etc.)									
Name	Name Signature Date								
Please complete and forward this form to:									
	Pilatus Aircraft LTD,								
		mer Technical Su	upport	(MCC),					
		BOX 992, Stans, Switzerlar	nd.						
		+41 (0)41 619 67							
		: Techsupport@p		aircraft.com					

SERVICE BULLETIN EVALUATION SHEET

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1. Date:
 Nov 30/12
 Page
 17 of 18





INTENTIONALLY BLANK

 Service Bulletin No:
 34-005
 Date:
 Sep 22/12

 Rev. No. 1. Date:
 Nov 30/12
 Page 18 of 18