



Lufttüchtigkeitsanweisung (LTA) Consigne de Navigabilité (CN) Direttive sulla Navigabilità (DN) Airworthiness Directive (AD)		FOCA AD <b>HB-2014-004</b>
Inkraftsetzung Mise en vigueur Entrata in vigore Effective Date	<b>02 October 2014</b>	<b>Pilatus – PC-9(M)</b> FOCA TC/TCDS No: F 56-32

**Issue Date:** 18 September 2014

**ATA Chapter:** ATA 52 – Doors

**Subject:** **Doors – Canopy Hinge Attachment Rivnuts – Inspection**

**Supersedure / Revised AD(s):** Not applicable

**Type Certificate Holder's Name:** Pilatus Aircraft Ltd.

**Manufacturer(s):** Pilatus Aircraft Ltd.

**Applicability:** Models PC-9(M) aircraft, Manufacturer Serial Numbers (MSN) 655 through MSN 670, originally delivered with a canopy assembly with Serial Number (S/N) 6409, 6411, 6414, 6425 through 6428, 6432, 6442 through 6445, 6453, 6454, 6456 and 6457.

**Reason:** This Airworthiness Directive (AD) is prompted due to a report that rivnuts in the canopy hinge attachments have not been correctly installed.

Such a condition, if left uncorrected, could lead to a canopy frame detaching from the hinge in flight, possibly resulting in reduced controllability of the aircraft.

In order to correct and control the situation, this AD requires a one-time check to identify the S/N of the canopy held in stock or installed in an aircraft and in case of a positive finding according to this AD, a borescope inspection of the canopy frame and corrective actions, if necessary.

**Required Action(s) and Compliance Time(s):** Required as indicated below, unless already accomplished:

NOTE 1: all steps of this AD must be performed within the next 365 days after the effective date of this AD. It is allowed to divide the individual steps of this AD over the year without the need of grounding the aircraft.

- (1) Identify the S/N of the canopies held in stock or installed in an aircraft. If no canopies with a S/N as referenced in this AD are found, no further action is needed.
- (2) If during the identification as required by paragraph (§) 1 of this AD any canopies with a S/N as referenced in this AD are found, perform a borescope inspection of the interior of the canopy frame as defined by § 3.B. of PILATUS PC-9(M) Service Bulletin No. 52-005. No rivnuts in cylindrical shape without a bulge are allowed.

Lufttüchtigkeitsanweisung (LTA) Consigne de Navigabilité (CN) Direttive sulla Navigabilità (DN) Airworthiness Directive (AD)	FOCA AD <b>HB-2014-004</b>
---	-------------------------------

- (3) If during the inspection as required by § (2) of this AD any rivnuts in cylindrical shape without a bulge are found, within the completion time of 365 days after the effective date of this AD or before the installation into an aircraft, continue with the rivnut installation process as required by § 3.C to 3.E of PILATUS PC-9(M) Service Bulletin No. 52-005.

**Ref. Publication(s):** PILATUS PC-9(M) Service Bulletin No. 52-005, initial issue.

The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.

**For further information contact:** The applicable manufacturer's documentation may be obtained directly from:

PILATUS AIRCRAFT LTD.  
Customer Technical Support (MCC)  
P.O. Box 992  
CH-6371 Stans, Switzerland

Tel.: +41 (0)41 619 67 74      Fax: +41 (0)41 619 67 73  
E-mail: [Techsupport@pilatus-aircraft.com](mailto:Techsupport@pilatus-aircraft.com)

For further information contact:

FEDERAL OFFICE OF CIVIL AVIATION (FOCA)  
Design and Production (STEH)  
CH-3003 Bern, Switzerland

Fax: +41 (0) 31 322 59 18  
E-mail: [airdir@bazl.admin.ch](mailto:airdir@bazl.admin.ch)