

**TEMPORARY REVISION NO. 11
TO PC-12 PILOT'S OPERATING HANDBOOK**

SYSTEMS AND EQUIPMENT LIMITS - AUTOPILOT

Record the incorporation of this Temporary Revision on the Log of Temporary Revisions.

SECTION 2 – LIMITATIONS

SYSTEMS AND EQUIPMENT LIMITS

AUTOPILOT

Page 2-27

There is a possibility that with the autopilot engaged an out of trim condition can occur when the flaps are at 40°. In the interim investigation period the following autopilot system limitation is added:

The autopilot must be disengaged before a flap selection to 40° is made.