

**TEMPORARY REVISION NO. 40  
TO PC-12 PILOT'S OPERATING HANDBOOK**

**SYSTEMS AND EQUIPMENT LIMITS - AUTOPILOT**

Record the incorporation of this Temporary Revision on the Log of Temporary Revisions.

**SECTION 2 – LIMITATIONS**

**SYSTEMS AND EQUIPMENT LIMITS**

**AUTOPILOT**

Page 2-22

There is a possibility that with the autopilot engaged an out of trim condition can occur when the flaps are at 40°. In the interim investigation period the following autopilot system limitation is added:

The autopilot must be disengaged before a flap selection to 40° is made.