

**PILATUS**  
**PC-9(M)**  
**MAINTENANCE MANUAL**

Task No.	Code	Task	Frequency
27507	P	Flap pivot arm assembly  Examine (Ref. 27-50-00, Page Block 601).	Threshold inspection at 30 April 2021 if installed before 30 April 2016, then every 5 years.  5 years if installed after 29 April 2016.
28106	P	Aerobatic Fuel Tank  Replace clamp (Ref. CMM 02082, 28-10-01, Page Block 7001)	6000 flying hours.
32108	P	Main Landing Gear Support Strut.  Examine. (Not Applicable if P/N 532.10.09.128 is installed), (Ref. 32-10-02, Page Block 601).	6 months.
35301	T	Oxygen Cylinder  Replace (maximum life) (Ref. 35-10-02, Page Block 401).	15 years.
35304	T	Oxygen Cylinder  Remove for hydrostatic test (Ref. 35-10-02, Page Block 401).	5 years.
53009	R1	Frame 3C to Longeron Connecting Bracket (Pre SB 53-005)  Examine (ejection seats, cockpit floor and side panels removed) (Ref. 53-10-03, Page Block 601).	2 years.
53011	P	Longerons  For aircraft older than 5 years, do a borescope inspection. (Ref. 53-10-05, Page Block 601).	At the next annual inspection then every 2 years.
53013	T4	Frame 3 pick-up bracket with P/N 553.10.09.075 or 553.10.09.076 (Post SB 51-001)  Do a borescope inspection on the Outboard Flange (Ref. 53-10-08, Page Block 601).	2 years.
53014	T4	Upper and Lower engine mount fitting with P/N 553.10.09.122 or 553.10.09.123 or 553.10.09.124 (Post SB 53-012).  Do a borescope inspection on the Outboard and Inboard Flange. (Ref. 53-10-07, Page Block 601).	1 year.

EFFECTIVITY: All

**05-05-01**

Page 2  
Feb 20/20