

PILATUS
PC-7 Mk II
MAINTENANCE MANUAL

Task No.	Code	Task	Frequency
25204	X	Emergency Oxygen Cylinder (Ejection Seat) Remove for overhaul (Ref. 25-10-07, Page Block 401).	5 years.
27507	X	Flap pivot arm assembly Examine (Ref. 27-50-00, Page Block 601).	Threshold inspection at 30 April 2021 if installed before 30 April 2016, then every 5 years. 5 years if installed after 29 April 2016.
28106	X	Aerobatic Fuel Tank Replace clamp (Ref. CMM 02082, 28-10-01, Page Block 7001).	6000 flying hours.
32108	V7	Main Landing Gear Support Strut. Examine. (Not Applicable if P/N 532.10.09.128 is installed), (Ref. 32-10-02, Page Block 601).	6 months.
32215	Z1	Landing Gear Door Microswitch with P/N 973.30.31.212, 973.30.31.211, 973.30.31.213 and 973.30.31.218 Replace (maximum life).	20000 landings.
35301	V1	Oxygen Cylinder Replace (maximum life) (Ref. 35-10-02, Page Block 401).	15 years.
35304	V1	Oxygen Cylinder Remove for hydrostatic test (Ref. 35-10-02, Page Block 401).	5 years.
53010	V4	Frame 3C to Longerons Connecting Bracket (Pre SB 53-006) Examine (ejection seats, cockpit floor and side panels removed) (Ref. 53-10-03, Page Block 601).	2 years.
53011	X	Longerons For aircraft older than 5 years, do a borescope inspection. (Ref. 53-10-05, Page Block 601).	At the next annual inspection then every 2 years.

EFFECTIVITY: All