

Bundesamt für Zivilluftfahrt (BAZL) Office fédéral de l'aviation civile (OFAC) Ufficio federale dell'aviazione civile (UFAC) Federal Office for Civil Aviation (FOCA) Maulbeerstrasse 9 CH-3003 Berne Switzerland	Lufttüchtigkeitsanweisung (LTA) Consigne de Navigabilité (CN) Prescrizione di Aeronavigabilità (PA) Airworthiness Directive (AD)	FOCA AD HB 99-347
Inkraftsetzung Mise en vigueur Entrata in vigore Effective Date	23.06.1999	PC-12 Series FOCA TC No.: F 56-30

URGENT – IMMEDIATE ACTION REQUIRED

Betroffene Muster - Types concernés - Applicabilità - Models affected

PILATUS AIRCRAFT LTD.

All Model PC-12 and PC-12/45 airplanes from MSN 101 up to and including MSN 320, equipped with windshields PILATUS P/N: 959.81.10.107 LH and 959.81.10.108 RH (PPG P/N: NP172121-5 LH and NP172121-6 RH). Affected windshields can be identified by the presence of three imbedded temperature sensors on the outboard edge of the windshield.

Anlass / Massnahmen - Objet / Mesures - Oggetto / Provvedimenti - Subject / Action

HEATED WINDSHIELD - WIRING ▪ Flight prohibition for affected aircraft.

Fristen - Délais- Scadenza – Compliance (as indicated, unless already accomplished)

Upon receipt – before further flight.

Herkunft - Provenance - Convenienza - Origin

FOCA Airworthiness Directive.

Bezugnahme - Référence - Riferimento - Reference

The manufacturer's documentation may be obtained directly from:

PILATUS AIRCRAFT LTD

MARKETING SUPPORT DEPARTMENT
CH-6370 STANS
SWITZERLAND

TEL. No.: +41 41 619 6233
FAX No.: +41 41 610 3351

Bemerkungen - Observations - Osservazioni - Remarks

- For details refer to page 2.

Rechtsmittelbelehrung Voies de droit Rimedi giuridici Right to appeal	siehe TM Nr. voir CT no. vedi CT no. see CT no.	02.020-80	Seite Page Pagina Page	von de di of	1	2
--	--	------------------	---------------------------------	-----------------------	----------	----------

