

PILATUS
PC-7 Mk II
MAINTENANCE MANUAL

MAINTENANCE TASKS			FREQUENCY			Air-worthiness Limitations
Task No.	Code	Task	150 Hr	300 Hr/ Annual	Out of Phase	
27507	X	Flap pivot arm assembly Examine. (Ref. 27-50-00, Page Block 601)			Threshold inspection at 30 April 2021 if installed before 30 April 2016, then every 5 years. 5 years if installed after 29 April 2016.	✓
27601	X	Airbrake Examine the airbrake structure, bonding, actuator, position microswitch and support bracket. Lubricate the bearings (Ref. 12-20-05, Page Block 301).	✓	✓		
27602	X	Airbrake Do a functional test (Ref. 27-60-00, Page Block 501).		✓		
27603	X	Airbrake Examine the actuator and hydraulic tubes and hoses.		✓		
27604	X	Airbrake Pitch Trim System Examine linkage and cable. Lubricate (Ref. 12-20-07, Page Block 301).		✓		
27606	X	Airbrake Pitch Trim System Do a functional test (Ref. 27-61-00, Page Block 501).		✓		
28101	X	Aerobatic Fuel Tank Remove for overhaul (Ref. 28-20-07, Page Block 401).			6000 flying hours. This time limit cannot be extended as given in 05-12-00 because of task 28106.	

EFFECTIVITY: All