



**Superseded by
FOCA AD
HB-2020-010**

| | |
|---|---|
| Lufttüchtigkeitsanweisung (LTA) Consigne de Navigabilité (CN) Direttive sulla Navigabilità (DN) Airworthiness Directive (AD) | FOCA AD HB-2012-005 |
| Inkraftsetzung Mise en vigueur Entrata in vigore Effective Date | 30 July 2012 Pilatus – PC-9(M) FOCA TC/TCDS No: F 56-32 |

Issue Date: 16 July 2012

ATA Chapter: ATA 05 – Time Limits / Maintenance Checks

Subject: **Time Limits / Maintenance Checks – Airworthiness Limitations – Amendment**

Supersedure / Revised AD(s): Not applicable

Type Certificate Holder's Name: Pilatus Aircraft Ltd.

Manufacturer(s): Pilatus Aircraft Ltd.

Applicability: Model PC-9(M) aircraft, all Manufacturer Serial Numbers (MSN).

Reason: This Airworthiness Directive (AD) is prompted by changes to the Airworthiness Limitations Section (ALS) of the Aircraft Maintenance Manual (AMM), which adds life-limits, revises life-limits or adds inspections not previously identified.

These documents include the maintenance instructions and/or airworthiness limitations developed by Pilatus Aircraft Ltd. and approved by FOCA. Failure to comply with these instructions and limitations could potentially lead to unsafe condition.

For the reasons described above, this AD requires the implementation and the compliance with these new or more restrictive maintenance requirements and/or airworthiness limitations.

Required Action(s) and Compliance Time(s): Required as indicated below, unless already accomplished:

- (1) Within the next 30 days after the effective date of this AD, comply with all applicable maintenance requirements and associated airworthiness limitations specified in the Pilatus PC-9(M) Airworthiness Limitation Section (ALS) page blocks 05-05-00 and 05-05-01 at revision 31 May 2012 or later approved issue, of the Aircraft Maintenance Manual (AMM) report n°02149.

Lufttüchtigkeitsanweisung (LTA)
Consigne de Navigabilité (CN)
Direttive sulla Navigabilità (DN)
Airworthiness Directive (AD)

FOCA AD
HB-2012-005

(2) Compliance with the requirements of paragraph (1) of this AD can be demonstrated by:

(2.1) Revising as follows, unless accomplished previously, the approved Aircraft Maintenance Programme from which the Operator or the Owner ensures the continuing airworthiness of each operated aircraft:

Incorporate applicable maintenance requirements and associated airworthiness limitations specified in the Pilatus PC-9(M) Airworthiness Limitation Section (ALS) page blocks 05-05-00 and 05-05-01 at revision 31 May 2012 or later approved issue, of the Aircraft Maintenance Manual (AMM) report n°02149,

and

(2.2) Complying with the approved Aircraft Maintenance Programme described in paragraph (2.1) of this AD.

Ref. Publication(s): PILATUS PC-9(M), AMM report n°02149 at revision 31 May 2012

The use of later approved revisions of this document is acceptable for compliance with the requirements of this AD.

For further information contact: The applicable manufacturer's documentation may be obtained directly from:

PILATUS AIRCRAFT LTD.
Customer Technical Support (MCC)
P.O. Box 992
CH-6371 Stans, Switzerland

Tel.: +41 (0)41 619 67 74 Fax: +41 (0)41 619 67 73
E-mail: Techsupport@pilatus-aircraft.com

For further information contact:

FEDERAL OFFICE OF CIVIL AVIATION (FOCA)
Design and Production (STEH)
CH-3003 Bern, Switzerland

Fax: +41 (0) 31 322 59 18
E-mail: airdir@bazl.admin.ch

Superseded by
FOGA AD
HB-2020-010